



Gjøco Gulv 40 oljebasert is a semi-gloss, durable floor paint based on urethane alkyd. To be used indoors on wood, parquet, laminate, floor coverings and concrete in dry rooms. Gjøco Poxylakk, Gjøco Poxylakk Ekstrem or GjøcoPoxylakk SL are used on new concrete floors and on floors that are exposed to high stress such as warehouse, other industrial floors as well as garages.

Physical data

Type:	Urethane alkyd
Colour:	Base A, B and C, tinted by using Gjøcomix
Gloss:	Semigloss 40
Specific gravity (kg/ltr):	Ca. 1,1
Solids by volume %:	Ca.55

Recommendation for use

Application methods:	Roller, brush or airless spray
Thinner / cleaning agent:	Water and a suitable cleaning agent
Recommended spreading rate:	8-10 m ² depending on surface
Guiding data for airless spray	
Nozzle tip:	0.53 mm (0.021")
Spray angle degrees:	65°- 80°
Pressure at nozzle:	Min. 15 mPa (Min. 150 kg/cm ²)
Drying times (23 °C, 50% R.H.):	
Dust dry:	4 hours. Drying time deviates at changes in temperature, air humidity, air circulation and film thickness.
Interval between coats (v/23°C), minimum:	Minimum 12 hours. Drying time deviates at changes in temperature, air humidity, air circulation and film thickness.
Minimum applying temp. °C:	+ 10°C. Best results are obtained by application at room temperature.
Cured:	4 weeks

Preparations

The substrate must be free of grease, oil and other contaminants. Previously painted floors are washed with Gjøco Gulv og Panelrens or another suitable cleaning agent. Glossy surfaces must be sanded. It is important to remove all sanding dust etc. to obtain good adhesion. Old untreated concrete floors must be sanded and cleaned before application. Porous old concrete floors can be saturated with diluted Gjøco Gulvolje.

For new concrete floors, warehouse floors, garages and other floors with high traffic, Gjøco Poxylakk, Gjøco Poxylakk Ekstrem or GjøcoPoxylakk SL are recommended.

How to apply

The paint should be stirred well before application. On untreated floors, thin the first coat with up to



20% white spirit before applying 1-2 coats of undiluted Gjøco Gulv 40 Oljebasert. Apply 2-3 coats depending on the substrate, evenly and thickly.

Colors

Use the same batch number on the same coat and the same surface, to avoid color and gloss differences. Cans where the color is mixed in on different mixing machines and/or at different times can produce shade differences. Be aware of this if more paint is needed for the same project afterwards.

Disposal of waste

Liquid paint must not be emptied into drains or watercourses. It must be delivered to an approved local environmental protection station.



Storage and transport

Keep the container frost free and upright.

Safety

For more detailed information, please refer to the safety datasheet. Read the information on the packaging. VOC: EU limit value for this product (category A/i): 500 g/l (2010). The product contains <500 g/l VOC.

Other information

Storage and transport: Upright, dry and frost-free. Application temperature in air and substrate must be at least + 10°C. Stir well before use. Different production numbers are mixed before use. Replace the lid well after use to prevent spillage and drying. Liquid paint must not be emptied into drains or watercourses, but delivered to the environmental protection station. For more detailed information, scan the QR code or look at www.gjoco.no.

The information in this document is given to the best of Gjøco's knowledge, based on laboratory testing and practical experience. Gjøco's products are considered as semi-finished goods and as such, products are often used under conditions beyond Gjøco's control. Gjøco cannot guarantee anything but the quality of the product itself. Minor product variations may be implemented in order to comply with local requirements. Gjøco reserves the right to change the given data without further notice.

Edited by Gjøco AS