

Product datasheet

Gjøco Supermatt Tak



Gjøco Supermatt Tak is a fully matt, water-thinnable, low-odour and non-reflective PVA paint. Used for priming and topcoating ceilings made of concrete, building boards, plaster, tissue and sand filler.

Revised

08.10.2025

Symbols



Technical data

Type:	PVA copolymer dispersion paint
Color:	White base, colors are mixed over Gjøcomix.
Gloss:	Flat
Specific gravity:	Ca. 1.35 kg/l
Application method:	Wide paint brush or felt roller. Spraying should be done by professionals.
Thinner/ cleaning agent:	Water, wash with soap and water.
Recommended film thickness, wet:	100 micrometer
Recommended film thickness, dry:	50 micrometer
Recommended spreading rate:	Ca. 10 m ² /litre, depending on the substrate.
Recommended data for airless spray:	
Nozzle tip:	0.43–0.53 mm (0.017–0.021")
Spray angle degrees:	50°-80°
Pressure at nozzle:	Follow the pump manufacturer's recommendations.
	The choice of nozzle, fan angle, and pressure must be adjusted to the specific spray equipment and substrate.
Drying times (23 °C, 50 % R.H.):	
Dry to use:	0.5 hours
Interval between coats:	3 hours. Full adhesion is achieved after 4 weeks of thorough curing. Varies with changes in temperature, humidity, ventilation and film thickness.
Minimum application temperature:	+5 °C. Best results are achieved when applied at room temperature.

Pretreatment	The substrate must be clean and dry before applying the paint. Semi-gloss and glossy surfaces should be dulled with sandpaper and dusted off. Surfaces with soot, grease and other contaminants should be washed clean with Gjøco Gulv og Panelrens or Gjøco Interiørvask. Follow the instructions on the packaging. Surfaces discolored by soot and nicotine, etc. should be primed with Gjøco Sperregrunn. Porous, sticky and absorbent surfaces should be brushed and primed with Gjøco Heftgrunn diluted with water.
Directions for use	Gjøco Supermatt Tak er ferdig til bruk og skal normalt ikke tynnes. Malingen røres godt om før bruk.
Color	Use the same batch number on the same coat and the same surface, to avoid gloss and color differences. Alternatively, different batch numbers can be mixed before use. Buckets where the color is mixed on different mixing machines and/or at different times can result in shade differences. Be aware of this if more paint is needed for the same project afterwards.
Storage	Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and frost-free.
Disposal of waste	Liquid paint must not be emptied into sewers or into nature, but delivered to an environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste. 
Ecolabelling	Gjøco Supermatt Tak is approved by Ecolabel Norway and meets the requirements for the Nordic ecolabel Svanen. 
Other information	The product must be stored in accordance with national regulations. The packaging must be kept tightly closed and stored dry at a constant temperature. Do not expose to frost. Packaging sizes: 2.7 and 9 liters
Safety	See separate safety data sheet. Read the information on the packaging. EU limit value for this product (cat. A/a): 30 g/l (2010). This product contains: <10 g/l VOC.

The information on this data sheet is based on laboratory tests and practical experience. Our products are considered semi-finished products and as the conditions under which the products are used are often beyond our control, we cannot guarantee anything other than the product's quality. The products are delivered in accordance with our general terms and conditions for sales, delivery and service, unless otherwise agreed in writing. We reserve the right to make minor product changes and to change the specified data without prior notice. This data sheet replaces previous editions.

Contact information

Gjøco AS
 Ørvegen 1160, 6639 Torvikbukt
 Telephone: +47 712 91 700
 E-mail: office@gjoco.no

