

Gjøco Fashion Oljemaling is a low-odour, matt and water-thinned oil paint for indoor use on wood. Provides a durable and smooth surface. Used as an intermediate and top coat on panelling, frames, mouldings, doors, MDF and furnishings.

## Physical data

Type:	Alkyd emulsion
Colour:	Base white, A, B and C, tinted by using Gjøcomix
Gloss:	Matt 05, silky 15, semigloss 40, glossy 80
Specific gravity (kg/ltr):	Ca. 1,1 – 1,3
Solids by volume %:	35 - 37

## Recommendation for use

Application methods:	Roller, brush or airless spray
Thinner / cleaning agent:	Water and a suitable cleaning agent
Recommended spreading rate:	8-10 m <sup>2</sup> depending on surface
Guiding data for airless spray	
Nozzle tip:	0.53 mm (0.021")
Spray angle degrees:	65° - 80°
Pressure at nozzle:	Min. 15 mPa (Min. 150 kg/cm <sup>2</sup> )
Drying times (23 °C, 50% R.H.):	
Dust dry:	1-2 hour. Drying time deviates at changes in temperature, air humidity, air circulation and film thickness.
Interval between coats (v/23°C), minimum:	6 hours. Drying time deviates at changes in temperature, air humidity, air circulation and film thickness.
Minimum applying temp. °C:	+ 10°C. Best results are obtained by application at room temperature.
Cured:	4 weeks

## Preparations

The surface must be clean and dry. Clean painted surfaces with Gjøco Interiørvask, then rinse well with water. MDF, hard surfaces, old semi-gloss or gloss paint must be sanded down and all dust removed. Prime all surfaces with one coat of Gjøco Sperregrunn (block primer). Make sure new wood and old discoloured/yellowing panelling are primed with minimum two coats of Gjøco Sperregrunn.

## How to apply

Apply two to three coats as required. Apply Gjøco Fashion thickly and smoothly. Use high quality painting tools to achieve a nice finish.

## Storage and transport

Keep the container frost free and upright.

## Colors

Use the same batch number on the same coat and the same surface, to avoid color and gloss differences. Cans where the color is mixed in on different mixing machines and/or at different times can produce shade differences. Be aware of this if more paint is needed for the same project afterwards.

## Disposal of waste

Liquid paint must not be emptied into drains or watercourses. It must be delivered to an approved local environmental protection station.



## Eco Labelling



Gjøco Fashion is approved by Ecolabelling Norway and meets the requirements for the Nordic Ecolabel

## Safety

For more detailed information, please refer to the safety datasheet. Read the information on the packaging. VOC: EU limit value for this product (category A/a): 30 g/l (2010). The product contains <1 g/l VOC.

## Other Information

Storage and transport: Upright, dry and frost-free. Application temperature in air and substrate must be at least + 10°C. Stir well before use. Different production numbers are mixed before use. Replace the lid well after use to prevent spillage and drying. Liquid paint must not be emptied into drains or watercourses, but delivered to the environmental protection station. For more detailed information, scan the QR code or look at [www.gjoco.no](http://www.gjoco.no).

The information in this document is given to the best of Gjøco's knowledge, based on laboratory testing and practical experience. Gjøco's products are considered as semi-finished goods and as such, products are often used under conditions beyond Gjøco's control. Gjøco cannot guarantee anything but the quality of the product itself. Minor product variations may be implemented in order to comply with local requirements. Gjøco reserves the right to change the given data without further notice.

Edited by Gjøco AS