

Gjøco Gulv Vanntynnbare is a water-thinnable flooring paint based on polyurethane-modified alkyd. The paint has good application properties, good flow and is very durable. Used indoors on wood, parquet, laminate, floor coverings and concrete in dry rooms. Suitable for use on ceramic tiles. Gjøco Poxydekk, Gjøco Poxydekk Ekstrem or GjøcoPoxy SL are used on new concrete floors and on stressed floor such as warehouse and other industrial floors as well as garages.

Physical data

Type:	Polyurethane-modified alkyd emulsion
Colour:	Base white, A, B and C, tinted by using Gjøcomix
Gloss:	Silky 15, semigloss 40
Specific gravity (kg/ltr):	Ca. 1,2
Solids by volume %:	38 - 40

Recommendation for use

Application methods:	Roller, brush or airless spray
Thinner / cleaning agent:	Water and a suitable cleaning agent
Recommended spreading rate:	8-10 m ² depending on surface
Guiding data for airless spray	
Nozzle tip:	0.53 mm (0.021")
Spray angle degrees:	65°- 80°
Pressure at nozzle:	Min. 15 mPa (Min. 150 kg/cm ²)
Drying times (23 °C, 50% R.H.):	
Dust dry:	2 hours. Drying time deviates at changes in temperature, air humidity, air circulation and film thickness.
Interval between coats (v/23°C), minimum:	Minimum 8 hours. Drying time deviates at changes in temperature, air humidity, air circulation and film thickness.
Minimum applying temp. °C:	+ 10°C. Best results are obtained by application at room temperature.
Cured:	4 weeks

Preparations

Wood/parquet/laminate: The substrate must be clean, dry and free of grease. Previously painted surfaces can be washed with Gjøco Gulv og Panelrens or a suitable cleaning agent, and rinsed with water. Old glossy and semi-gloss paint must be sanded down and dust removed. Untreated, sanded or old wooden floors are first treated with Gjøco Sperregrunn (see separate recommendations for this product). Then apply 2-3 coats of Gulv Vanntynnbare. Old laminate floors do not normally need priming. New laminate floors may contain substances that make overpainting difficult, do a test coat.

Ceramic tiles: The substrate must be clean, dry and free of grease. Clean with Gjøco Gulv og Panelrens or a suitable cleaning agent, and rinse with water. Smooth and hard tiles must be lightly

sanded with fine sandpaper to ensure adhesion. The paint can be applied directly without the use of a primer. If priming is desired, Gjøco Sperregrunn is recommended.

Concrete: Gjøco Gulv Vanntynnbare is suitable as a paint for older untreated concrete floors and previously painted concrete floors in dry rooms without heavy traffic. The substrate must be clean, dry and free of grease and oil residues, on previously painted surfaces loose paint must be removed and cleaned with Gjøco Gulv og Panelrens or a suitable cleaning agent. Old glossy or semi-gloss paint must be sanded and dust be removed. It is important to remove all sanding dust etc. to obtain good adhesion. Old untreated concrete floors should be sanded before application.

For new concrete floors, warehouse floors, garages and other floors with high loads, Gjøco Poxydekk, Gjøco Poxydekk Ekstrem or GjøcoPoxy SL are recommended.

How to apply

Apply two to three coats as required. Apply Gjøco Gulv Vanntynnbare thickly and smoothly. Use high quality painting tools to achieve a nice finish.

Colors

Use the same batch number on the same coat and the same surface, to avoid color and gloss differences. Cans where the color is mixed in on different mixing machines and/or at different times can produce shade differences. Be aware of this if more paint is needed for the same project afterwards.

Disposal of waste

Liquid paint must not be emptied into drains or watercourses. It must be delivered to an approved local environmental protection station.



Storage and transport

Keep the container frost free and upright.

Safety

For more detailed information, please refer to the safety datasheet. Read the information on the packaging. VOC: EU limit value for this product (category A/i): 140 g/l (2010). The product contains <80 g/l VOC.



Other Information

Storage and transport: Upright, dry and frost-free. Application temperature in air and substrate must be at least + 10°C. Stir well before use. Different production numbers are mixed before use. Replace the lid well after use to prevent spillage and drying. Liquid paint must not be emptied into drains or watercourses, but delivered to the environmental protection station. For more detailed information, scan the QR code or look at www.gjoco.no.

The information in this document is given to the best of Gjøco's knowledge, based on laboratory testing and practical experience. Gjøco's products are considered as semi-finished goods and as such, products are often used under conditions beyond Gjøco's control. Gjøco cannot guarantee anything but the quality of the product itself. Minor product variations may be implemented in order to comply with local requirements. Gjøco reserves the right to change the given data without further notice.

Edited by Gjøco AS
