

Product datasheet

Gjøco Oljegrunning



Gjøco Oljegrunning is a light thixotropic primer for exterior wood and is based on penetrating alkyds and oils. Contains film preservative against black fungus. Gjøco Oljegrunning is ideal for priming bare exterior wood of spruce and pine. Can also be used on impregnated wood.

Revised 10.12.2024

Symbols




Technical data

Type:	Primer based on alkyd oils
Color:	Clear and white
Flash point:	>62 °C
Specific gravity:	0.89 kg/l
Solid content:	Approx. 42 volum%
Application method:	Brush. Do not spray.
Thinner / cleaning agent:	White Spirit
Film thickness, wet:	80 mikrometers
Film thickness, dry:	20 mikrometers
Recommended spreading rate:	
Planed wood:	6-10 m ² /liter
Unplaned wood:	4-8 m ² /liter
Drying time (23 °C, 50 % R.H.):	Depends on temperature, humidity, wind and film thickness.
Dust dry:	2 hours
Interval between coats, minimum:	24 hours
Minimum application temperature:	Can be used below +5 °C, but the substrate must be dry and frost-free. Low temperatures will significantly extend the drying time.

Pretreatment

The substrate must be clean and dry. New wood that has been untreated for more than 4 weeks must be wire brushed before applying Gjøco Oljegrunning. Vacuum-impregnated windows must be degreased before priming. Round off sharp edges to achieve the best possible edge coverage. Smooth and hard surfaces such as planed wood can be lightly sanded before priming. Previously painted wood must be scraped clean of loose paint, and weathered surfaces must be wire brushed

	down to fresh wood. Grease and other contaminants must be removed with Gjøco Husvask.
Directions for use	The product is ready to use and should not be thinned. New and untreated wood should be treated with Gjøco Oljegrunning as soon as possible after installation. Bare wood should be given one coat. Use a wide brush. Remember to saturate end wood and joints with 3-4 coats. Further treatment should be carried out as soon as possible and within 1 month. Gjøco Oljegrunning should not form a film; any excess should be wiped off with a lint-free cloth.
Storage	Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and frost-free.
Disposal of waste	Liquid stain should not be emptied into sewers or into the environment, but delivered to an approved hazardous waste collection point. Empty, clean and dry packaging should be delivered to an approved collection point. 
Other information	Any oil that has risen in the can should be stirred in for a while before use. Clear oil primer is recommended under transparent stain, because pigmented oil primer can cause color changes. Feel free to do a test coat. Packaging sizes: 0.75; 3 and 10 liters.
Safety	See separate safety data sheet. Read the information on the packaging. EU limit value for this product (kat. A/h): 700 g/l (2010). This product contains: <500 g/l VOC.

The information on this data sheet is based on laboratory tests and practical experience. Our products are considered semi-finished products and as the conditions under which the products are used are often beyond our control, we cannot guarantee anything other than the product's quality. The products are delivered in accordance with our general terms and conditions for sales, delivery and service, unless otherwise agreed in writing. We reserve the right to make minor product changes and to change the specified data without prior notice. This data sheet replaces previous editions.

Contact information **Gjøco AS**
 Ørvegen 1160, 6639 Torvikbukta
 Telephone: +47 712 91 700
 E-mail: office@gjoco.no

