Product data sheet

Gjøco Proff Gulv- og vegglim





Gjøco Proff Gulv- og vegglim is a water-based glue for floor coverings and wall cladding in dry and wet rooms. It is suitable for floor coverings and carpets with or without foam backing, cork with PVC backing, and wall cladding with a minimum 0.6 mm PVC layer. Gjøco Gulv- og Vegglim is not recommended for linoleum or standard wallpaper.

Revised	27.11.2024		
Symbols		TVANIN- TYNNBAR A	
			Marine News
Technical Data	Туре:	PVA dispersion	
	Color:	White	
	Density:	Approx. 1,3 kg/l	
	Solids Content:	Approx. 70% by volume	
	Application Method	Apply with a notched trowel	
	Thinner / Cleaning Agent	Water. Wet glue and tools can be cleaned with soap and water. Dried glue can be removed with rubbing alcohol.	
	Recommended Coverage:	Approx. 4-6 m²/liter, depending on the s	ubstrate
	Minimum Application Temperature	Minimum +18°C in the air and on the surface	
Preparation	The surface must be clean and dry. Any unevenness should be filled and sanded before applying the glue.		
Usage Instructions	Stir well before use. Follow the instructions from the manufacturer of the floor or wall covering. Apply the glue with a notched trowel, using a glue bead height of approximately 2-3 mm. For absorbent substrates, the covering should be applied within 30 minutes on wet glue. For non-absorbent surfaces and wall applications, allow the glue to dry for 45–80 minutes until it no longer feels wet to the touch before applying the covering. Ensure the covering is pressed firmly onto the surface, and that air is squeezed out.		
Storage	Seal the lid tightly when storing the glue to prevent spills and drying out. Store and transport upright, frost-free, and preferably not below +10°C.		
Waste Disposal	Liquid glue and wash water should not be poured into drains or released into nature. They should be delivered to an approved hazardous waste collection point. Empty, clean, and dry plastic packaging without handles can be disposed of as plastic waste.		





Additional Information Stir well before use. Wet glue and tools can be washed with soap and water.

Dried glue can be removed mechanically or with rubbing alcohol.

Packaging Sizes: 1 and 5 liters

Safety Refer to the dedicated safety data sheet. Read the information on the packaging.

The information in this data sheet is based on laboratory tests and practical experience. Our products are considered semi-finished goods, and since the conditions under which they are used are often beyond our control, we can only guarantee the quality of the product itself. The products are supplied in accordance with our general terms of sale, delivery, and service unless otherwise agreed in writing. We reserve the right to make minor product modifications and to change the stated data without prior notice. This data sheet supersedes previous versions.

Contact Information Gjøco AS

Ørvegen 1160, 6639 Torvikbukt Phone number: +47 712 91 700

Email: office@gjoco.no

