## Product datasheet Gjøco Gulv 15 Vanntynnbar

27.11.2024





Gjøco Gulv 15 is a water-thinnable floor paint based on polyurethane-modified alkyd. The paint has good application properties, good flow and is very durable. Used indoors on wood, parquet, laminate, floor coverings and concrete in dry rooms. Suitable for use on ceramic tiles. On newly poured floors and on stressed floor surfaces such as warehouse and industrial floors and garages, use Gjøco Poxydekk, Gjøco Poxydekk Ekstrem or GjøcoPoxy SL.

## **Technical data**

Revised

Symbols

Туре:	Water-thinnable oil paint based on polyurethane
Color:	White, A, B and C base, colors are mixed over Gjøcomix.
Gloss:	Eggshell 15
Specific gravity:	Ca. 1.2 kg/l
Solid content:	38 – 40 volum%
Application method:	Wide paint brush or felt roller. Spraying should be done by professionals.
Thinner/ cleaning agent:	Water
Guide data high-pressure sprayer:	
Nozzle:	0,021"; 0,53 mm
Fan angle:	65-80°
Paint pressure:	150 kg/cm <sup>2</sup>
Recommended spreading rate:	6 – 8 m²/litre
Drying times (23 °C, 50 % R.H.):	
Dry to use:	2 hours
Interval between coats:	Min. 8 hours. Full adhesion is achieved after 4 weeks of thorough curing. Varies with changes in temperature, humidity, ventilation and film thickness.
Minimum application temperature:	+10 °C. Best results are achieved when applied at room temperature.

## Pretreatment

Wood/parquet/laminate: The substrate must be clean, dry and free of grease. Previously painted surfaces can be washed with Gjøco Floor and Panel Cleaner or a suitable cleaning agent, and rinsed with water. Old glossy and semi-gloss

Floor and Panel Cleaner or a suitable cleaning agent. Old glossy or semi-gloss paint must be mattified with sandpaper. Vacuum and wipe with a lint-free cloth, preferably microfiber. It is important to remove all sanding dust etc. to achieve good adhesion. Old untreated concrete floors should be sanded before application.   For newly poured floors, warehouse floors, garages and other floors with heavy loads, Gjøco Poxydekk, Gjøco Poxydekk Ekstrem or GjøcoPoxy SL are recommended.   Directions for use Gjøco Gulv 15 water-thinnable is ready to use and should not normally be thinned. Stir well and apply 2-3 coats depending on the substrate. Apply evenly and generously.   Color Use the same batch number on the same coat and the same surface, to avoid gloss and color differences. Alternatively, different batch numbers can be mixed before use. Buckets where the color is mixed on different mixing machines and/or at different times can result in shade differences. Be aware of this if more paint is needed for the same project afterwards.   Storage Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and frost-free.   Disposal of waste Liquid paint must not be emptied into sewers or into nature, but delivered to an environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste.   Objoss and color differences. Mortar (MS joint compound) and similar joint compounds for ship floors, etc. can affect the drying time of the paint. Take a test coat. Should not be used on linoleum flooring and old floor coverings. If necessary, take a test coat to check that the paint dries and the result is as expected.		
Gjøco Floor and Panel Cleaner or a suitable cleaning agent, and rinse with water.   Smooth and hard tiles must be sanded lightly with fine sandpaper to ensure adhesion. The paint can be applied directly without the use of a primer. If priming is desired, Gjøco Sperregrunn is recommended.   Concrete: Floor 15 water-thinnable is suitable as a paint for older untreated concrete floors and previously painted concrete floors in dry rooms without heavy loads. The substrate must be clean, dry and free of grease and oil residues, on previously painted surfaces, loose paint must be removed and cleaned with Gjøco Floor and Panel Cleaner or a suitable cleaning agent. Old glossy or semi-gloss paint must be mattified with sandpaper. Vacuum and wipe with a lint-free cloth, preferably microfiber. It is important to remove all sanding dust etc. to achieve good adhesion. Old untreated concrete floors should be sanded before application.   For newly poured floors, warehouse floors, garages and other floors with heavy loads, Gjøco Gulv 15 water-thinnable is ready to use and should not normally be thinned. Stir well and apply 2-3 coats depending on the substrate. Apply evenly and generously.   Color Use the same batch number on the same coat and the same surface, to avoid gloss and color differences. Alternatively, different batch numbers can be mixed before use. Buckets where the color is mixed on different mixing machines and/or at different tast applied and stored upright, dry and free.   Norage Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and freet.   Norage Store dry and frost-free. Stir well before use. Mix different batch numbers to avoid gloss and color differences. Nortar (MS joi		must first be treated with Gjøco Sperregrunn (see separate recommendations for this product). Then treat with 2-3 coats of Gulv 15 water-thinnable. Old laminate floors do not need a primer. New laminate floors may contain substances that
concrete floors and previously painted concrete floors in dry rooms without heavy loads. The substrate must be clean, dry and free of grease and oil residues, on previously painted surfaces, loose paint must be removed and cleaned with Gjaco Floor and Panel Cleaner or a suitable cleaning agent. Old glossy or semi-gloss paint must be mattified with sandpaper. Vacuum and wipe with a lint-free cloth, preferably microfiber. It is important to remove all sanding dust etc. to achieve good adhesion. Old untreated concrete floors should be sanded before application.   For newly poured floors, warehouse floors, garages and other floors with heavy loads, Gjaco Poxydekk, Gjaco Poxydekk Ekstrem or GjacoPoxy SL are recommended.   Directions for use Gjaco Gulv 15 water-thinnable is ready to use and should not normally be thinned. Stir well and apply 2-3 coats depending on the substrate. Apply evenly and generously.   Color Use the same batch number on the same coat and the same surface, to avoid before use. Buckets where the color is mixed on different mixing machines and/or at different times can result in shade differences. Be aware of this if more paint is needed for the same project afterwards.   Storage Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and frost-free.   Disposal of waste Liquid paint must not be emptied into sewers or into nature, but delivered to an environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste.   Ois of ship floors, due dool differences. Mix different batch numbers to avoid gloss and color differences. Stir well before use. Mix different batch numbers to avoid gloss and color differ		Gjøco Floor and Panel Cleaner or a suitable cleaning agent, and rinse with water. Smooth and hard tiles must be sanded lightly with fine sandpaper to ensure adhesion. The paint can be applied directly without the use of a primer. If priming
Ioads, Gjøco Poxydekk, Gjøco Poxydekk Ekstrem or GjøcoPoxy SL are recommended.   Directions for use Gjøco Gulv 15 water-thinnable is ready to use and should not normally be thinned. Stir well and apply 2-3 coats depending on the substrate. Apply evenly and generously.   Color Use the same batch number on the same coat and the same surface, to avoid gloss and color differences. Alternatively, different batch numbers can be mixed before use. Buckets where the color is mixed on different mixing machines and/or at different times can result in shade differences. Be aware of this if more paint is needed for the same project afterwards.   Storage Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and frost-free.   Disposal of waste Liquid paint must not be emptied into sewers or into nature, but delivered to an environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste.   Other information Store dry and frost-free. Stir well before use. Mix different batch numbers to avoid gloss and color differences. Mortar (MS joint compound) and similar joint compounds for ship floors, etc. can affect the drying time of the paint. Take a test coat. Should not be used on linoleum flooring and old floor coverings. If necessary, take a test coat to check that the paint dries and the result is as expected. Packaging sizes: 0.68 and 2.7 liters		concrete floors and previously painted concrete floors in dry rooms without heavy loads. The substrate must be clean, dry and free of grease and oil residues, on previously painted surfaces, loose paint must be removed and cleaned with Gjøco Floor and Panel Cleaner or a suitable cleaning agent. Old glossy or semi-gloss paint must be mattified with sandpaper. Vacuum and wipe with a lint-free cloth, preferably microfiber. It is important to remove all sanding dust etc. to achieve good adhesion. Old untreated concrete floors should be sanded before application.
thinned. Stir well and apply 2-3 coats depending on the substrate. Apply evenly and generously.   Color Use the same batch number on the same coat and the same surface, to avoid gloss and color differences. Alternatively, different batch numbers can be mixed before use. Buckets where the color is mixed on different mixing machines and/or at different times can result in shade differences. Be aware of this if more paint is needed for the same project afterwards.   Storage Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and frost-free.   Disposal of waste Liquid paint must not be emptied into sewers or into nature, but delivered to an environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste.   Disposal of waste Store dry and frost-free. Stir well before use. Mix different batch numbers to avoid gloss and color differences. Mortar (MS joint compound) and similar joint compounds for ship floors, etc. can affect the drying time of the paint. Take a test coat. Should not be used on linoleum flooring and old floor coverings. If necessary, take a test coat to check that the paint dries and the result is as expected.   Packaging sizes: 0.68 and 2.7 liters		loads, Gjøco Poxydekk, Gjøco Poxydekk Ekstrem or GjøcoPoxy SL are
gloss and color differences. Alternatively, different batch numbers can be mixed before use. Buckets where the color is mixed on different mixing machines and/or at different times can result in shade differences. Be aware of this if more paint is needed for the same project afterwards.   Storage Seal the lid tightly when storing paint to prevent spillage and drying. The paint must be transported and stored upright, dry and frost-free.   Disposal of waste Liquid paint must not be emptied into sewers or into nature, but delivered to an environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste.   Disposal of waste Store dry and frost-free. Stir well before use. Mix different batch numbers to avoid gloss and color differences. Mortar (MS joint compound) and similar joint compounds for ship floors, etc. can affect the drying time of the paint. Take a test coat. Should not be used on linoleum flooring and old floor coverings. If necessary, take a test coat to check that the paint dries and the result is as expected. Packaging sizes: 0.68 and 2.7 liters	Directions for use	thinned. Stir well and apply 2-3 coats depending on the substrate. Apply evenly
must be transported and stored upright, dry and frost-free.   Disposal of waste Liquid paint must not be emptied into sewers or into nature, but delivered to an environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste.   Image: Comparison of the paint information Store dry and frost-free. Stir well before use. Mix different batch numbers to avoid gloss and color differences. Mortar (MS joint compound) and similar joint compounds for ship floors, etc. can affect the drying time of the paint. Take a test coat. Should not be used on linoleum flooring and old floor coverings. If necessary, take a test coat to check that the paint dries and the result is as expected.   Packaging sizes: 0.68 and 2.7 liters	Color	gloss and color differences. Alternatively, different batch numbers can be mixed before use. Buckets where the color is mixed on different mixing machines and/or at different times can result in shade differences. Be aware of this if more paint is
environmental station. Empty, clean, and dry plastic packaging without a handle can be delivered as plastic waste.	Storage	
gloss and color differences. Mortar (MS joint compound) and similar joint compounds for ship floors, etc. can affect the drying time of the paint. Take a test coat. Should not be used on linoleum flooring and old floor coverings. If necessary, take a test coat to check that the paint dries and the result is as expected. Packaging sizes: 0.68 and 2.7 liters	Disposal of waste	environmental station. Empty, clean, and dry plastic packaging without a handle
Safety See separate safety data sheet. Read the information on the packaging.	Other information	gloss and color differences. Mortar (MS joint compound) and similar joint compounds for ship floors, etc. can affect the drying time of the paint. Take a test coat. Should not be used on linoleum flooring and old floor coverings. If necessary, take a test coat to check that the paint dries and the result is as expected.
	Safety	See separate safety data sheet. Read the information on the packaging.

EU limit value for this product (cat. A/)i: 140 g/l (2010). This product contains: <80 g/l VOC.

The information on this data sheet is based on laboratory tests and practical experience. Our products are considered semi-finished products and as the conditions under which the products are used are often beyond our control, we cannot guarantee anything other than the product's quality. The products are delivered in accordance with our general terms and conditions for sales, delivery and service, unless otherwise agreed in writing. We reserve the right to make minor product changes and to change the specified data without prior notice. This data sheet replaces previous editions.

## Contact information

**Gjøco AS** Ørvegen 1160, 6639 Torvikbukt Telephone: +47 712 91 700 E-mail: office@gjoco.no

