## Product data sheet Gjøco Proff Våtromslim



Gjøco Proff Våtromslim is a water-based adhesive for indoor use in wet rooms. It is used for bonding vinyl, PVC, and fiberglass fabric to particleboard, wood, concrete, and gypsum. It should not be used on floors. Iron may corrode when in contact with the adhesive.

c] (ø) (

Revised

27.11.2024

Symbols

**Technical Data** 

Туре:	PVA emulsion
Color:	White
pH:	Approx. 7
Density:	Approx. 1,04 kg/l
Solids Content:	Approx. 34% by volume
Application Method	Applied with a notched trowel, brush, or a lint-free roller
Thinner / Cleaning Agent	Water. Wet glue and tools can be cleaned with soap and water Dried glue can be removed with rubbing alcohol.
Recommended Coverage:	Approx. 4 m <sup>2</sup> per liter, depending on the substrate
Overpaintable:	Minimum 24 hours
Minimum Application Temperature	+15°C. Minimum +15°C in both the air and on the surface.

The surface must be clean and dry. Uneven areas should be filled with Gjøco Våtromssparkel and then sanded smooth. Highly absorbent substrates should be primed with Gjøco Våtromslim diluted with 3 parts water.

 Usage Instructions
 The adhesive should always be applied according to the wallpaper manufacturer's instructions. Standard use: For vinyl wallpaper, allow the adhesive to dry for 10-15 minutes before hanging. For heavier materials, apply the adhesive directly to the wall. For lighter materials (e.g., vinyl), apply the adhesive to the wallpaper, allowing it to dry for a few minutes before hanging. Working temperature: Minimum +15°C in both air and on the substrate. The adhesive is applied with a notched trowel, brush, or a lint-free roller.

Storage

Preparation

Keep the lid tightly closed when storing the adhesive to prevent spillage and drying out. Store and transport the product upright and frost-free, preferably not below +10°C.

Waste Disposal	Liquid adhesive and wash water should not be poured into drains or released into nature. They should be delivered to an approved hazardous waste collection point. Empty, clean, and dry plastic packaging without handles can be disposed of as plastic waste.	
Additional Information	Stir well before use. Wet glue and tools can be washed with soap and water. Dried glue can be removed mechanically or with rubbing alcohol. Packaging Sizes: 1 and 5 liters	
Safety	Refer to the dedicated safety data sheet. Read the information on the packaging.	
conditions under which they are used a accordance with our general terms of s	ased on laboratory tests and practical experience. Our products are considered semi-finished goods, and since the are often beyond our control, we can only guarantee the quality of the product itself. The products are supplied in sale, delivery, and service unless otherwise agreed in writing. We reserve the right to make minor product I data without prior notice. This data sheet supersedes previous versions.	
Contact Information	Gjøco AS Ørvegen 1160, 6639 Torvikbukt Phone number: +47 712 91 700 Email: office@gjoco.no	