

FDV - Management, Operation and Maintenance **GjøcoPur T**



GjøcoPur T is a solvent-free, flexible 2-component PU coating designed for high-wear floor systems, such as parking garages, warehouses, or production facilities. It is intended for use as a topcoat and is available in multiple colors.

Concrete substrates must always be primed before further coating; see the system description in the GjøcoPark System or the technical data sheets for GjøcoPoxy BP, GjøcoPoxy Universal (EKO), or GjøcoPoxy MF. The product can also be used on steel.

Revised	14.10.2025	
Application Instructions	Substrate:	The substrate must be solid, clean, dry, and free of grease, with a temperature of at least +12 °C for both substrate and air, and at least 3 °C above the current dew point. Lower temperatures will extend the curing time.
	Application method:	Notched trowel or leveling rake, followed by rolling.
	Thinner:	The product must not be thinned.
	Storage:	The product must be stored dry and frost-free, and in accordance with national regulations. The packaging must be kept tightly closed and stored in a dry place at a stable temperature. The product must be transported and stored upright, dry, and frost-free.
	Indoor environment / emissions:	The product has low emissions.
Product Data Sheet and Safety Data Sheet	A product data sheet and safety data sheet (SDS) have been prepared for the product. See www.gjoco.no.	
Maintenance	Cleaning:	Before repainting, Gjøco Gulv og Panelrens or another suitable cleaning agent is recommended. Follow the instructions on the product. When applying a new coating, the substrate should be lightly sanded to ensure adhesion. See the product data sheet for additional information.
	Interval:	The coating is affected by mechanical stress and wears depending on the level of use. Maintenance intervals will therefore vary according to need.

Waste Management

Liquid thermoset resin must not be poured into drains or released into the environment but should be delivered to a recycling or waste collection station. Cured thermoset resin can be disposed of at waste collection stations as residual waste, but it is recommended to contact the local facility for specific guidance, as regulations may vary locally.







Repairs / Damage

Repairs and damage should be remedied using the same type of product. If other products are used, it must be documented that they are of the same type as previously applied. When repairing damage, the work should be carried out so that it does not differ from previous treatments. For repainting or color changes, it is recommended to use the same product as before. Contact the supplier or painting company.

Treated Surface / Type of Substrate:	
Painted in Color:	Color Name:
	NCS:
Batch Number:	
Painting Work Performed By	y:
Date:	
Signature:	

The information in this data sheet is based on laboratory tests and practical experience. Our products are considered semi-finished, and since the conditions under which they are used are often beyond our control, we can only guarantee the quality of the product itself. The products are supplied in accordance with our general terms of sale, delivery, and service, unless otherwise agreed in writing. We reserve the right to make minor product modifications and to change the specified data without prior notice. This data sheet replaces previous editions and is automatically void five years after the date of issue.

Contact Information

Gjøco AS, Galterud Sagmoen 100, NO-2223 Galterud, Norway Phone: +47 712 91 700

Email: office@gjoco.no

